

December 2012

SPOT -C-Progress Report





### **CONTENTS**

### 1. INTRODUCTION

- a. Introduction
- b. Project brief
- c. Project particulars

### 2. EXECUTIVE SUMMARY

a. Project construction main data

### 3. PROGRESS OVER VIEW

a. Progress of works

#### 4. PHOTOS



1.

#### a. INTRODUCTION

The progress report is an assessment that takes place during a project or process, that conveys details such as what sub-goals have been accomplished, what resources have been expended, what problems have been encountered, and whether the project or process is expected to be completed on time and within budget.

It is intended to be a proactive decision- making document; a separate section on actions and alerts has been highlighted for each action along the due dates.

This report also provides a streamlined analysis of the actual, planned and forecasted events of the project.

The executive summary will provide brief information on the project status.

The general progress overview will provide details on progress achieved to date on the project. The progress that is reported encompasses time, cost, quality, risk, scope, procurement, resources, and safety management.



### b. PROJECT BRIEF

Function: Shopping center Built up area: 125500 sq. m.


Location: Choueifat, Lebanon

The concept was to create a well organized circulation space based on 3 axis intersected on the main plaza. The evolution of these axis gave rise to the final shape of the building (by dividing the main shape into 4 volumes.


The complex consists of:


- a. Retail spaces.
- b. Cinemas space.
- c. Amusement center.
- d. Terraces.

### Below are some views of the project's exterior views:









































### c. PROJECT PARTICULARS

Project Title: Choueifat Mall CM

Location: Choueifat, Lebanon

Developer: B.A. Choueifat BA

Main Contractor: Dolmen contracting DC

Shoring subcontractor-1 DST DST

Shoring subcontractor-2 MGM MGM

Consultant DNA DNA

Technical Control Socotec STC

Building Materials Consultant 3PE-3<sup>rd</sup> Party 3PE


Engineering



## 2. EXECUTIVE SUMMARY

### PROJECT CONSTRUCTION MAIN DATA

Project Start Date	January 2012
Project Finish Date (preliminary)	December 2015
Project Duration	1445
Days Elapsed	291
Percentage Of days elapsed	20.1 %





## 3. PROGRESS OF WORKS

Subcontractor	description	Work completed	Comment
H. Salman	Excavation - top of footings	95%	
	Excavation - footings	Zone A: 100%	
		Zone B: 95%	
		Zone C: 70%	
		Zone D: 45%	
DST	Shoring system	100%	
MGM	Shoring system	100%	



### 4. PHOTOS

The following section provides some indicative idea on progress of works that were conducted by the main contractor.

They are not necessarily demonstrating all activities of works that were carried out during the period of the report.



## DOLTICI





# DOLMEN





# DOLTICA





## DOLMEN





# DOLTICI





# DOLTO





# DOLTICI



